

Technical Service
Bulletin Number

Revision Level

Date

Group Number

TSB120001

SB-10044175-4287



Technical Service Bulletin

Subject

New Oil Fill Cap and Seal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

A new engine oil fill cap with an integrated seal has been released for ISX11.9 and ISX15 engines. The new design prevents loss of the seal and also provides a positive stop for the fill cap when installed onto the oil fill neck.

The new assembly was fully implemented in production on September 29, 2011. The engine serial number (ESN) first for this change is 79514809. New parts are available for service repair locations and can be ordered separately from the complete oil fill assembly.

The new part obsoletes and supersedes the previous cap and seal as shown in the table below.

New and Obsoleted Part Numbers			
New Part Number	Description	Obsolete Part Number	Description
	Cap, filler (with		

3687932	integrated seal)	2869221	Cap, filler
3687932	Cap, filler (with integrated seal)	3686728	Seal, rectangular ring

Document History

Date	Details
2012-1-2	Module Created

Last Modified: 10-Jan-2012