Technical Service Bulletin

Topic	Potential spurious Diagnostic Trouble Code (DTC)
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2043466/2
Level	EH
Status	Released for publishing
Release date	Aug 9, 2016

Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
0007 - Display Control Unit	00003: Control module	0: tbd	static

New customer code

Object of complaint	Complaint type	Position
Information, navigation, communication, entertainment -> Settings -> Set date -> Set date format	Functionality -> Not adjustable	

New workshop code

Object of complaint	Complaint type	Position
Power, vehicle electrical system, data transfer -> Databus systems -> Programmable special functions control module	Control modules, services -> Data incorrect	

Vehicle data

Bentayga

Sales types

Туре	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	Е		*	*	*

Chassis numbers

Manufacturer	Filler	Туре	Filler	MY	Factory	From	То	Prod from	Prod to
SJA	***	**	*	Η	С	000001	999999		

Control units

Diagnostic address	Software part number	Software version	Hardware part number	Hardware version
0007 - Display Control Unit	36A.907.156.A	0091	36A.907.156	H33
0007 - Display Control Unit	36A.907.156	0091	36A.907.156	H33
0007 - Display Control Unit	36A.907.156	0093	36A.907.156	H33

Technical Service Bulletin 2043466/2

0007 - Display Control Unit	36A.907.156.A	0093	36A.907.156	H33
0009 - Central Electrics	4M0.907.063.G	0144	4M0.907.063.G	H12
0009 - Central Electrics	8W0.907.063.G	0215	4M0.907.063.G	H12
0009 - Central Electrics	8W0.907.063.G	0215	8W0.907.063.G	H12
0009 - Central Electrics	8W0.907.063.AG	0228	8W0.907.063.G	H12

Documents

Document name

master.xml

Technical Service Bulletin

Potential spurious Diagnostic Trouble Code (DTC)

Transaction No.: 2043466/2

Release date: Aug 9, 2016

Condition

Customer will not be aware of these codes / Workshop may discover codes whilst running a Diagnostic Trouble Code log as part of other investigations on the car

Technical Background

Due to software maturity on selected ECUs the following codes may be seen in service. The code is stored without being accompanied by any functional failure in the system

Production Solution

Service

The following may be seen during routine interrogation of vehicle systems do not take any investigative action in response to the following fault code unless there is an actual fault evident in the system or a fault in the system has been reported by the owner.

Address 07 – Display Control Unit

U200003_IPA_ - keine Kommunikation

Status: Static

Address 09 – Central Electrics (BCM1)

B1928F0 - Parallel parking assistance not available Parking assistance coded wrong

Status: Static